LEUNG KAI FOOK MEDICAL COMPANY (PTE) LTD

Seepage Rectification Works

GENO LIM / 8189 3693

ADDRESS: BLK 1001 JLN BUKIT MERAH #03-10, S159455

EMAIL: kaiba.gc@gmail.com



Reg No: T17LP0074F



Contents

F:	C	^	1:4:
FXISTING	Seepage	l ana	IITION
LVISHIP	Jechage		

Window Seepage Condition 03

External Wall Seepage Condition 04


Seepage Rectification Works

Window Seepage Rectification Works 05

External Wall Seepage Rectification 06

Water seepage through window frame and worn-off sealant between concrete and window frame







EXISTING SEEPAGE CONDITION



Drilling hole into window frame and pump Polyurethane foam to fill hollowness inside frame



SEEPAGE RECTIFICATION WORKS

